Ple	ease print or type. (Form of	designed for use on el	lite (12-pitch) typew	riter.)	1	£1.		need ent	16	For	m Approve	d. OMB No	2050-003	
	WASTE MANIFEST					age 1 of 3. Emergency Response Phone				4. Manifest Tracking Number 008037341 FLE				
	5. Generator's Name and Mailing Address Generator's Site Address (if different than mailing address)  25.45 North New York Street Wichta KS 67219  Generator's Phone:													
	6. Transporter 1 Company Name								U.S. EPA ID I	U.S. EPA ID Number				
	7. Transporter 2 Company Name									U.S. EPA ID Number				
GENERATOR	8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40385 S County Road 230 Warroka, OK 73860 Facility's Phone: 15801 697-3100									U.S. EPA ID Number  OKD 0 6 5 4 3 8 3 7 6				
							10. Containers No. Type			12. Unit Wt./Vol.	13. Waste Codes			
	1.WA3077 F	IAZARDOUS W	ASTE, SOLID	, N.O.S., (F(	001, F003).	2 20 2	INU.	туре	Quantity	TALI VOI.	F001	F002	F003	
	K PG III							BU	16	V	F004	F005	4.5	
	2.									1				
	3.	10.00							- 70			1.15		
	4.				. 45								1 1	
	14. Special Handling Instru		ormation RG\$171		116				- 1.		17.1		-	
				TRAT	124			T	LH		1246		, A	
	15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent.  I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.													
	append append					ature		and him			Mo	onth Day	Year	
<u></u> →	16. International Shipments	Import to		3	Export from U	) AAA	Port of en	trulovity (			ti	6 64	10	
INT'L	Transporter signature (for e	exports only):	10,		Export norm o	φ.	Date leavi		4.7	1-17				
<b>TEF</b>	17. Transporter Acknowledgment of Receipt of Materials  Transporter 1 Printed/Typed Name Signature Month Day Year													
TR ANSPORTER	Hommi Carh						AND THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	was Lie.		D21081/5				
	Transporter 2 Printed/Typed	I Name			'Sign	ature	Sp. 10		*		Mo	onth Day	Year	
<u>F</u>	18. Discrepancy								31-6		. /		1 1 1	
	18a. Discrepancy Indication Space Quantity Type Residue Partial Rejection Full Rejection													
	Manifest Reference Number:													
Ē	18b. Alternate Facility (or G	enerator)							U.S. EPA ID N	umber				
FAC	Facility's Phone:		1 1 1 1 1 1 1 1 1											
<ul> <li>DESIGNATED FACILITY</li> </ul>	18c. Signature of Alternate I	-acility (or Generator)									M	onth Day	y Year	
	19. Hazardous Waste Repo	rt Management Method (	Codes (i.e., codes for l	hazardous waste tr	reatment, disposal,	and recycling	systems)		n en	. / /				
	1. N132		2.		3.				4.					
	20. Designated Facility Own	er or Operator: Certificat	tion of receipt of hazar	dous materials cov			noted in Iten	n 18a		1	15-	_ [[		
$\downarrow$	Printed/Typed Name	i Dear	by to ad	(	Sign	aure		13	lande!	Line-	1 I	onth Day	Year	